## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Docket No.: 2309.1004-000










Docket No.: 2309.1004-000






Fig. 3(a)

Docket No.: 2309.1004-000

Independent X/Y Flow Adjustable ... ors: Hans Groeblacher et al.





Fig. 3(b)

Title: Independent X/Y Flow Adjustable entors: Hans Groeblacher et al.



Docket No.: 2309.1004-000

Title: Independent X/Y Flow Adjustable ntors: Hans Groeblacher et al.




Fig 9(b)

2309.1004-000

Docket No.: 2309.1004-000
le: Independent X/Y Flow Adjustable ventors: Hans Groeblacher et al.





Fig. **5** 

Docket No.: 2309.1004-000

le: Independent X/Y Flow Adjustable Ventors: Hans Groeblacher et al.



79

FIG 53